



Fig. 4. *Macroscopic evaluation of the cartilage lesion – original chondral defect compared with the same lesion after microfracture + PRP/MSCs (as detected during a second-look arthroscopy). A bioptic sample was harvested for histological evaluation.*